

NETWORK 1275 Danner Dr Tel:330-562-7070 TECHNOLOGIES Aurora, OH 44202 Fax:330-562-1999 INCORPORATED www.networktechinc.com

Installing an Unsigned Driver in Windows 8 (x64)

When trying to load the USB driver into a Windows 8 PC in order to use the USB Console port on an NTI product, you may encounter a window that prevents it because it is an "unsigned driver", in spite of the fact it is actually a Microsoft driver from an earlier operating system.

The steps to enable the installation of the USB driver on Windows 8 are as follows:

1. From Windows 8 Control Panel choose General -> Under "Advanced Startup" -> Restart now.

Now the system will restart and might take some minutes to show up the boot menu. Wait for It patiently.

After some time you will be prompted with a menu with the following options.

- 1. Continue
- 2. Troubleshoot
- 3. Turn off

2. Choose Troubleshoot

Then the following menu appears:

Refresh your PC Reset your PC Advanced Options

3. Choose Advanced Options

Then the following menu appears:

System Restore System Image Recovery Automatic Repair Command Prompt Windows Startup settings

4. Choose Windows Startup Settings, then Click Restart.

Now the computer will restart and the boot menu appears.

5. Choose "Disable Driver Signature Enforcement" from the boot menu.

Now Windows will start and you can follow the instructions in the product manual for the installation of the USB driver.